ICS 233 – Computer Architecture
& Assembly Language

Assignment 6: Single-Cycle Processor Implementation

1. **(5 pts)** Describe the effect that a single stuck-at-0 fault (i.e., the signal is always 0 regardless of what it should be) would have for the signals shown below, in the single-cycle Datapath. Which instructions, if any, will not work correctly? Explain why.

   Consider each of the following faults separately:

   a) RegWrite = 0
   b) RegDst = 0
   c) ALUScr = 0
   d) MemtoReg = 0
   e) Branch = 0

2. **(5 pts)** Repeat question 1 but this time consider stuck-at-1 faults (the signal is always 1).

3. **(6 pts)** We wish to add the instruction **jalr** (jump and link register) to the single-cycle datapath. Add any necessary datapath and control signals and draw the result datapath. Show the values of the control signals to control the execution of the **jalr** instruction.

   The jump and link register instruction is described below:

   ```
   jalr rd, rs  # rd = pc + 4 , pc = rs
   ```

$op^6 = 0$	rs^5	0	rd^5	0	$func^6 = 9$

4. **(4 pts)** We want to compare the performance of a **single-cycle CPU design** with a **multi-cycle CPU**. Suppose we add the multiply and divide instructions. The operation times are as follows:

   Instruction memory access time = 190 ps,   Data memory access time = 190 ps
   Register file read access time = 150 ps,   Register file write access = 150 ps
   ALU delay for basic instructions = 190 ps,   ALU delay for multiply or divide = 550 ps

   Ignore the other delays in the multiplexers, control unit, sign-extension, etc.

   Assume the following instruction mix: 30% ALU, 15% multiply & divide, 20% load, 10% store, 15% branch, and 10% jump.

   a) What is the total delay for each instruction class and the clock cycle for the single-cycle CPU design

   b) Assume we fix the clock cycle to 200 ps for a multi-cycle CPU, what is the CPI for each instruction class and the speedup over a fixed-length clock cycle?